

VEHICLE INSPECTION REPORT


KHF105

Gardner 6LX Engine *For Spares or Repair*

Inspection		Vehicle		
		VAT	Margin	
		V5	N/A	
Details				
Location	Onsite Customer Auction	Mileage	Not Showing	VIN
		Fuel Type		
Reg. date		Colour		
Year				
Tyres				
NSF				
NSR				
OSF				
OSR				
Spare				

Photos





Commercial Vehicle Auctions Limited