

VEHICLE INSPECTION REPORT

LP69NLY

Volkswagen Crafter 2.0 TDI 140PS Trendline

Inspection

Serious Damage? No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	41539
Cap Code	VWCR205M4THDTM2 1 L

Details

Location	Doncaster	GVW	3500kg	CAP Clean	£4,225.00
Reg. date	06/02/2020	Colour	GREEN	CAP Average	£3,700.00
Year	2020	VIN	WV1ZZSYZL9027490	CAP Below	£2,925.00
Mileage	223,441 Miles Warranted	Body Style	Panel Van	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	05/02/2027	Gears	6

WARNING LIGHTS ON DASH E/MIRRORS, AD-BLUE

Tyres

NSF

NSR

OSF

OSR





Spare


Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Park assist camera
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage

2: Bonnet
Chipped
Multiple Chips



3: Panel Front
Cracked
Replace

4: Wing nsf
Dented
With Paint Damage




5: Wing nsf
Dented
With Paint Damage

6: Wing nsf
Dented
With Paint Damage



7: Door nsf
Dented
With Paint Damage

8: Door nsf
Dented
With Paint Damage



9: Door nsf
Dented
With Paint Damage

10: Door nsf
Dented
Over 30mm




11: Door nsf
Scratched
Over 25mm Thru Paint

12: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



13: Qtr Panel nsr
Dented
Over 30mm

14: Qtr Panel nsr
Dented
With Paint Damage





15: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

16: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm



17: Door Moulding nsf
Missing
Replace

18: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



19: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

20: Door osr
Dented
With Paint Damage



21: Qtr Panel osr
Dented
With Paint Damage



22: Qtr Panel osr
Scratched
Over 25mm Thru Paint



23: Qtr Panel osr
Dented
With Paint Damage



24: Qtr Panel osr
Dented
With Paint Damage



25: Qtr Panel osr
Dented
With Paint Damage



26: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm





27: Door osf
Dented
With Paint Damage

28: Door osf
Chipped
Multiple Chips



29: Wing osf
Dented
With Paint Damage

30: Screen Front
Cracked
Replace



31: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		