

VEHICLE INSPECTION REPORT

FJ17RFK

Mercedes-Benz Actros 1824

Non Runner

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Cap Code 999900

Details

Location Bedford

GVW 18000kg

Gearbox AUTOMATIC

Reg. date 05/06/2017

Colour WHITE

Axle Combi 4x2

Year 2017

VIN WDB96300320145725

Rear Suspension Air

Mileage 745,663 Km Not Warranted

Body Style Curtainside

Rear Doors Barn

Fuel Type DIESEL

Cab Type BIGSPACE CAB

Tail Lift Tuckaway

NON RUNNER-TURBO BLOWN, MAJOR OIL LEAK

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3



OSO4

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Broken
Replace



2: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



3: Door Mirror Assy nsf
Broken
Replace



4: Bumper Rear
Rusted
Over 5mm



5: Door nsr
Scratched
Over 25mm Thru Paint



6: Door osr
Cracked
Replace



7: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm



8: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



9: Door osf
 Scratched
 UpTo 25mm Thru Paint



10: Door osf
 Chipped
 Edge Chip



11: Seat Base Cover osf
 Holed
 Over 3mm



12: Seat Back Cover osf
 Torn
 Over 3mm

Interior

Carpet Condition
Seat Condition

Average
 Average

Engine Runs Fault

Upholstery Condition
Odour

Average
 -