

VEHICLE INSPECTION REPORT

NK73YJX

Mercedes-Benz Sprinter 3.5t H2 Progressive Van

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present
		Cap Id	49244
		Cap Code	MESP2053PGHDTM2 5 L

Details

Location	Livingston	GVW	3500kg	CAP Clean	£18,150.00
Reg. date	21/11/2023	Colour	WHITE	CAP Average	£16,800.00
Year	2023	VIN	W1V3HCFZ5RP600085	CAP Below	£14,450.00
Mileage	81,434 Miles Warranted	Body Style	Panel Van	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	20/11/2026	Gears	6

WARNING LIGHT ON DASH, POWER STEERING INOP SIDE LOAD DOOR, AD-BLUE.

Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Radio/CD
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A



2: Bonnet
Dented
Over 30mm



3: Roof
Rusted
Over 5mm



4: Bonnet
Missing
Replace



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



6: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



7: Qtr Panel osr
Dented
Over 30mm



8: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



9: Qtr Panel osr
Dented
Over 30mm



10: Tailgate
Dented
With Paint Damage



11: Bumper Rear Moulding
Broken
Replace



12: Bumper Reflector nsr
Missing
Replace



13: Qtr Panel nsr
Dented
With Paint Damage



14: Qtr Panel nsr
Dented
With Paint Damage



15: Door nsr
Dented
With Paint Damage

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition			Odour		
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Turbo Boosting		OK	Gearbox Static Gear Selection (engine running)		OK
Parking Brake		OK	No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK
Windows		OK	Radio		OK
			Steering		OK