

VEHICLE INSPECTION REPORT

G25HNA

Land Rover Discovery 3.0 SDV6 HSE

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present
Cap Id	62289
Cap Code	LRDI30SHS5WDTA4 3

Details

Location	Bedford	Colour	WHITE	CAP Below	£4,875.00
Reg. date	17/12/2015	VIN	SALLAAAG5GA801422	Gearbox	AUTOMATIC
Year	2015	Body Style	Estate	Gears	8
Mileage	142,304 Miles Not Warranted	MOT Due	13/03/2027	Doors	5
Fuel Type	DIESEL	CAP Clean	£6,500.00		
GVW	3260kg	CAP Average	£5,675.00		

ENGINE NOT RUNNING ON ALL CYLINDERS E/MIRRORS, CLIMATE CONTROL, HEATED SEATS, KEYLESS IGNITION

Tyres




NSF
NSR
OSF
OSR
Spare


Features

- Front parking sensor
- Air conditioning
- Alloy wheels
- Park assist camera
- Front electric windows
- Rear parking sensor
- Rear electric windows
- Body coloured bumpers
- Leather seat trim


Photos







Condition Check



Damage Photos




1: Wing osf
Chipped
1 To 5

2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
UpTo 25mm Not Thru Paint

4: Wing Front Arch Extension ns
Scratched (Painted)
UpTo 25mm Thru Paint



5: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint

6: Door nsr
Chipped
1 To 5



7: Bumper Rear
Dented
With Paint Damage

8: Rear TowEye Cvr
Missing
Replace



9: Qtr Panel Arch Extension os
 Scratched (Painted)
 Over 25mm Thru Paint

10: Door Mirror Assy osf
 Scratched (Painted)
 Over 25mm Not Thru Paint



11: Door osr
 Scratched
 UpTo 25mm Thru Paint

12: Door osr
 Scratched
 UpTo 25mm Thru Paint

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK