

VEHICLE INSPECTION REPORT

BY67LNZ

Mercedes-Benz Antos 1824

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present
		Cap Code	999900

Details

Location	Bedford	GVW	18000kg	Cab Type	DAY CAB
Reg. date	18/09/2017	Colour	WHITE	Gearbox	AUTOMATIC
Year	2017	VIN	WDB96300320116192	Axle Combi	4x2
Mileage	295,067 Km Not Warranted	Body Style	Skiploader	Rear Suspension	Air
Fuel Type	DIESEL	MOT Due	31/03/2027		

HYVALIFT GEAR, SURROUND CAMERA SYSTEM, SHEETING SYSTEM

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Park assist camera
- Air conditioning

Photos





Condition Check



Damage Photos



1: Wing of
Scratched
Over 25mm Not Thru Paint



2: Screen Front
Chipped
Over 10mm



3: Bonnet
Chipped
Multiple Chips



4: Bumper Front
Dented
With Paint Damage



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



6: Wing nsf
Scratched
Over 25mm Not Thru Paint



7: Wing Front Arch Extension nsf
Scuffed (Unpainted)
Over 100mm



8: Door Mirror Assy nsf
Broken
Replace



9: Bumper Rear
Rusted
Over 5mm



10: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm



11: Door osf
Chipped
Multiple Chips



12: B Post os
Scratched
UpTo 25mm Thru Paint



13: Door osf
Scratched
Over 25mm Not Thru Paint



14: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs		OK		Gearbox 1st and Reverse Test		OK	
Brakes		OK		Clutch Slip Test from Static		OK	
Parking Brake		OK		Gearbox Static Gear Selection (engine running)		OK	
				No Excessive Smoking		OK	
EML light illuminated		OK		Oil warning light illuminated		OK	
Airbag light illuminated		OK		DPF light illuminated		OK	
ABS light illuminated		OK		Service indicator light illuminated		OK	