

VEHICLE INSPECTION REPORT

HN67NVE

Daf LF 230

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Cap Code 999900

Details

Location Avonmouth

Reg. date 10/11/2017

Year 2017

Mileage 119,222 Km Not Warranted

Fuel Type DIESEL

GVW 16000kg

Colour ORANGE

VIN XLRAEL2700L469588

Body Style Dropside

MOT Due 31/10/2026

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Steel

WARNING LIGHT ON DASH, LIMP MODE


Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Bluetooth connection
- Navigation system
- Auxiliary input socket
- Digital radio
- Radio/CD
- Drivers airbag
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Bonnet
Chipped
Over 5mm



3: Moulding nsf Wing
 Scratched (Painted)
 Over 25mm Thru Paint



4: Bumper Front
 Scratched
 Over 100mm Thru Paint



5: Door Mirror Assy nsf
 Missing
 Replace



6: Door nsf
 Chipped
 Over 5mm



7: Door nsf
 Chipped
 Edge Chip



8: Qtr Panel Arch Extension ns
 Scuffed (Unpainted)
 Over 100mm



9: Qtr Panel nsr
Chipped
Over 5mm



10: Qtr Panel nsr
Dented
Over 30mm



11: Qtr Panel nsr
Chipped
Over 5mm



12: Qtr Panel nsr
Dented
Over 30mm



13: Qtr Panel nsr
Chipped
Over 5mm



14: Qtr Panel nsr
Dented
Over 30mm



15: Qtr Panel nsr
Chipped
Over 5mm



16: Lamp nsr
Broken
Replace



17: Tailgate
Chipped
Multiple Chips



18: Tailgate
Dented
Over 30mm



19: Reflector nsr
Broken
Replace



20: Qtr Panel osr
Chipped
Multiple Chips



21: Qtr Panel osr
Chipped
Over 5mm



22: Qtr Panel osr
Dented
Over 30mm



23: Qtr Panel osr
Chipped
Over 5mm



24: Qtr Panel osr
Dented
Over 30mm



25: Qtr Panel osr
Hole
Over 10mm



26: Qtr Panel osr
Chipped
Over 5mm



27: Qtr Panel osr
Dented
Over 30mm



28: Panel Rear
Dented
Over 30mm



29: Panel Rear
Chipped
Over 5mm



30: Door osf
Chipped
Multiple Chips



31: Door osf
Scratched
Over 25mm Thru Paint



32: Door osf
Chipped
Multiple Chips



33: Roof
Dented
Over 30mm



34: Moulding osf Wing
Scratched (Painted)
Over 25mm Thru Paint




35: Moulding osf Wing
Broken
Replace



36: Bumper Front
Insecure
Action Required



37: Seat Base Cover osf
Torn
Over 3mm



38: Seat Base Cover nsf
Torn
Over 3mm



39: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running)		OK
			No Excessive Smoking		OK
EML light illuminated		Fault	DPF light illuminated		OK
Airbag light illuminated		OK			
ABS light illuminated		OK			
Sat nav		OK	Radio		OK