

VEHICLE INSPECTION REPORT

HN67NVF

DAF LF 230

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Cap Code 999900

Details

Location Avonmouth

Reg. date 17/11/2017

Year 2017

Mileage 115,019 Km Not Warranted

Fuel Type DIESEL

GVW 16000kg

Colour ORANGE

VIN XLRAEL2700L469681

Body Style Dropside LWB

MOT Due 30/11/2026

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Steel

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4


Spare NSO1 NSO2 NSO3 NSO4

OSO1 OSO2 OSO3 OSO4

Features

- Navigation system

Condition Check



Damage Photos



1: Seat Base Cover nsf
Torn
Over 3mm

2: Fascia Trim
Damaged
Replace



3: Seat Back Cover osf
Torn
Over 3mm

4: Screen Front
Cracked
Replace



5: Bonnet
Chipped
Multiple Chips

6: Moulding nsf Wing
Scratched (Painted)
Over 25mm Thru Paint



7: Bumper Front
Cracked
Over 25mm

8: Door nsf
Scratched
Over 25mm Thru Paint




9: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint

10: Door nsf
Dented
With Paint Damage



11: Qtr Panel nsr
Dented
With Paint Damage

12: Qtr Panel Trim ns
Missing
Replace



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint

14: Door osf
Dented
With Paint Damage



15: Moulding of Wing
Scratched (Painted)
Over 25mm Thru Paint

16: Moulding of Wing
Scratched (Painted)
Over 25mm Thru Paint



17: Bumper Front
Scratched
Over 100mm Thru Paint

18: Door of
Dented
With Paint Damage

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		