

VEHICLE INSPECTION REPORT

WX20KNJ

Fiat Ducato 140 35 2.3 MULTIJET I

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow
		Cap Id	44846
		Cap Code	FIDU233MM4HDTM2 5 L

Details

Location	Doncaster	Colour	WHITE	CAP Average	£5,450.00
Reg. date	29/06/2020	VIN	ZFA25000002N99959	CAP Below	£4,400.00
Year	2020	Body Style	Panel Van LWB	Gearbox	MANUAL
Mileage	90,924 Miles Warranted	Service history	None	Gears	6
Fuel Type	DIESEL	MOT Due	04/07/2027		
GVW	3500kg	CAP Clean	£6,225.00		

COLLECTED AS A NON-RUNNER LIMP MODE WARNING LIGHTS ON DASH E/MIRRORS

Tyres




NSF
NSR
OSF
OSR
Spare

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Front parking sensor
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Over 5mm



2: Door osf
Chipped
Over 5mm



3: Sill os
Chipped
Edge Chip



4: Fuel Flap
Scratched
Over 25mm Not Thru Paint



5: Panel Front
Scratched
Over 25mm Not Thru Paint



6: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



7: Seat Base Cover osf
Torn
Over 3mm



8: Carpets Front
Torn
Over 10mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK