

VEHICLE INSPECTION REPORT

WS19ADU

Fiat Ducato 35 II 2.3 MULTIJET 130PS

Inspection

Serious Damage? No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	31282
Cap Code	FIDU2335M3HDTM2 5 L

Details

Location	Doncaster	GVW	3500kg	CAP Clean	£4,350.00
Reg. date	22/08/2019	Colour	WHITE	CAP Average	£3,750.00
Year	2019	VIN	ZFA25000002L52329	CAP Below	£2,925.00
Mileage	112,960 Miles Warranted	Body Style	Panel Van	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	17/07/2027	Gears	6

E/ MIRRORS

Tyres

NSF

NSR

OSF


OSR




Spare

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Front parking sensor
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Panel Front
Chipped
Multiple Chips



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



4: Door Mirror Assy nsf
Broken
Replace




5: Door nsf
Scratched
Over 25mm Thru Paint



6: Sill ns
Rusted
Holed



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Dented
Over 30mm



9: Qtr Panel nsr
Chipped
Multiple Chips



10: Door osr
Chipped
Multiple Chips



11: C Post os
Dented
With Paint Damage



12: C Post os
Dented
With Paint Damage



13: Qtr Panel osr
Dented
With Paint Damage



14: Door osf
Chipped
Multiple Chips



15: Qtr Panel osr
Chipped
Multiple Chips



16: Door Pad osf
Soiled
Heavy



17: Carpets Front
Holed
Over 3mm



18: Seat Base Cover osf
Torn
Over 3mm



19: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		