

VEHICLE INSPECTION REPORT

AL67LNZ

Mercedes-Benz Antos

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Cap Code 999900

Details

Location Doncaster

Reg. date 18/09/2017

Year 2017

Mileage 308,738 Km Not Warranted

Fuel Type DIESEL

GVW 18000kg

Colour WHITE

VIN WDB96300320116193

Body Style Skiploader

Service history None

MOT Due Expired

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 4x2

Rear Suspension Air

HYVALIFT BODY, MODEL NG20212XL, SHEETING SYSTEM

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2



OSO3




OSO4

Features

- Bluetooth connection
- Digital radio
- Cloth seat trim
- Cruise control
- Air conditioning
- Park assist camera
- Front electric windows
- Auxiliary input socket
- Central locking


Photos







Condition Check



Damage Photos



1: Screen Front
Chipped
UpTo 10mm



2: Panel Front
Scratched
Over 25mm Thru Paint



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



4: Door osf
Chipped
Over 5mm



5: Door osf
Scratched
Over 25mm Thru Paint



6: Door osf
Scratched
Over 25mm Thru Paint



7: Door osf
Chipped
Edge Chip



8: Door osf
Scratched
UpTo 25mm Thru Paint



9: Moulding nsf Wing
Scratched (Painted)
Over 25mm Thru Paint



10: Grille Front
Broken
Replace



11: Moulding nsf Wing
Broken
Replace



12: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition		Average	
Seat Condition		Poor	
Engine Runs	OK	Upholstery Condition	Average
Brakes	OK	Odour	-
Turbo Boosting	OK	Gearbox 1st and Reverse Test	OK
Parking Brake	OK	Clutch Slip Test from Static	OK
EML light illuminated	OK	Gearbox Static Gear Selection (engine running)	OK
Airbag light illuminated	OK	No Excessive Smoking	OK
ABS light illuminated	OK	Oil warning light illuminated	OK
Windows	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK
		Radio	OK
		Steering	OK

