

VEHICLE INSPECTION REPORT

BX09GBF

Daf LF 45.180

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow
		Cap Code	999900

Details

Location	Bedford	GVW	7500kg	Gearbox	MANUAL
Reg. date	24/08/2009	Colour	WHITE	Axle Combi	4x2
Year	2009	VIN	XLRAE45FF0L352901	Rear Suspension	Steel
Mileage	244,470 Km Warranted	Body Style	Box Van	Rear Doors	Roller
Fuel Type	DIESEL	Cab Type	DAY CAB	Tail Lift	Column






WORKSHOP AREA IN REAR, SINGLE SIDE BARN DOOR

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Photos







Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Not Thru Paint



2: Screen Front
Chipped
UpTo 10mm



3: Bumper Front
Dented
With Paint Damage



4: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



6: Qtr Panel nsr
Scratched
UpTo 25mm Not Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint



8: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



9: Wing Front Arch Extension os Scuffed (Unpainted) Over 100mm



10: Seat Base Cover osf Holed Over 3mm

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Parking Brake	OK			Gearbox Static Gear Selection (engine running)	OK		
				No Excessive Smoking	OK		
EML light illuminated	OK			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	OK		
ABS light illuminated	OK			Service indicator light illuminated	OK		