

VEHICLE INSPECTION REPORT

CP21KYV

Iveco Daily 72-180

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply
		Cap Code	999900

Details

Location	Bedford	GVW	7200kg	Cab Type	DAY CAB
Reg. date	05/07/2021	Colour	WHITE	Gearbox	MANUAL
Year	2021	VIN	ZCFC670D50D668613	Axle Combi	4x2
Mileage	64,361 Km Not Warranted	Body Style	Tipper	Rear Suspension	Steel
Fuel Type	DIESEL	MOT Due	31/07/2027		

WARNING LIGHTS ON DASH

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Park assist camera

Photos





Condition Check



Damage Photos



1: Panel Front
Poor Previous Repair
Poor Colour



2: Wing nsf
Scratched
UpTo 25mm Thru Paint



3: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



4: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



5: Qtr Panel osr
Scratched
Over 25mm Thru Paint



6: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



7: Bonnet
Dented
Over 30mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running)		OK
			No Excessive Smoking		OK
EML light illuminated		Fault	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		Fault
ABS light illuminated		OK	Service indicator light illuminated		OK