

VEHICLE INSPECTION REPORT

HN63CVP

Iveco Eurocargo 120EL18

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Cap Code 999900

Details

Location Doncaster

Reg. date 04/12/2013

Year 2013

Mileage 167,781 Km Not Warranted

Fuel Type DIESEL

GVW 12000kg

Colour ORANGE

VIN ZCFA1ED0402617475

Body Style Dropside

MOT Due 31/12/2026

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Steel

WARNING LIGHTS ON DASH

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Auxiliary input socket
- Digital radio
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Panel Front
Scratched
Over 25mm Thru Paint



2: Bumper Front
Rusted
Over 5mm



3: Screen Front
Chipped
UpTo 10mm



4: Screen Front
Chipped
UpTo 10mm



5: Moulding of Wing
Scratched (Painted)
Over 25mm Thru Paint



6: Panel Front
Dented
With Paint Damage



7: Door of
Scratched
Over 25mm Thru Paint



8: Door of
Chipped
Edge Chip



9: Door osf
Chipped
Edge Chip



10: Door nsf
Scratched
Over 25mm Thru Paint



11: Door nsf
Scratched
Over 25mm Thru Paint



12: Door nsf
Scratched
Over 25mm Thru Paint



13: Door nsf
Chipped
Edge Chip



14: Seat Base Cover osf
Holed
UpTo 3mm

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Poor		Odour		-	
Engine Runs		OK		Gearbox 1st and Reverse Test		OK	
Brakes		Fault		Clutch Slip Test from Static		OK	
Turbo Boosting		OK		Gearbox Static Gear Selection (engine running)		OK	
Parking Brake		OK		No Excessive Smoking		OK	
EML light illuminated		OK		Oil warning light illuminated		OK	
Airbag light illuminated		OK		DPF light illuminated		OK	
ABS light illuminated		OK		Service indicator light illuminated		OK	
Windows		OK		Radio		OK	
				Steering		OK	