

VEHICLE INSPECTION REPORT

DK17LJE

Man TGS 26.360

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow
		Cap Code	999900

Details

Location	Bedford	GVW	26000kg	Cab Type	DAY CAB
Reg. date	31/08/2017	Colour	BLUE	Gearbox	MANUAL
Year	2017	VIN	WMA18SZZ1HM744028	Axle Combi	6x2
Mileage	148,162 Km Warranted	Body Style	Dropside & Crane	Rear Suspension	Air
Fuel Type	DIESEL	MOT Due	31/07/2027		

SERVICE SCHEDULE LIST AVAILABLE, HMF 1420K REMOTE CRANE (YEAR 2017), REAR LIFT, SURROUND CAMERA SYSTEM


Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Park assist camera


Photos







Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



2: Wing of
Scratched
Up To 25mm Thru Paint



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



4: A Post ns
Scratched
Up To 25mm Not Thru Paint



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



6: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



7: Door nsf
Dented
With Paint Damage



8: Door nsf
Chipped
Edge Chip



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Bumper Rear
Rusted
Over 5mm



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: Door osf
Scratched
Over 25mm Thru Paint



13: Door osf
Chipped
Edge Chip



14: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm



15: Seat Base Cover osf
Holed
Over 3mm



16: Handle Inner osf
Damaged
Replace



17: Switches And Controls
Broken
Replace

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average	Odour	Average
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		