

VEHICLE INSPECTION REPORT

WR20DVJ

Fiat Ducato 35 2.3 Multijet 140

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow
		Cap Code	FIDU233MM4HDTM2 5 L

Details

Location	Doncaster	GVW	3500kg	MOT Due	28/06/2027
Reg. date	29/06/2020	Colour	WHITE	Gearbox	MANUAL
Year	2020	VIN	ZFA25000002N99208	Gears	6
Mileage	111,011 Miles Warranted	Body Style	Panel Van LWB		
Fuel Type	DIESEL	Service history	None		


AD-BLUE, E/MIRRORS





Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Front parking sensor
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front Moulding
Broken
Replace




3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



4: Qtr Panel nsr
Dented
With Paint Damage



5: Qtr Panel nsr
Dented
Over 30mm



6: Door osr
Dented
With Paint Damage



7: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



8: Qtr Panel osr
Dented
Over 30mm



9: Seat Base Cover osf
Soiled
Heavy



10: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	Average	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		