

# VEHICLE INSPECTION REPORT

**KY16SXZ**

## Isuzu D-Max A314 2.5TD

| Inspection      |    | Vehicle  |                |
|-----------------|----|----------|----------------|
| Serious Damage? | No | VAT      | Plus VAT       |
|                 |    | V5       | Buyer To Apply |
|                 |    | Cap Id   | 24961          |
|                 |    | Cap Code | ISDM25 PDTM4 L |

### Details

|           |                   |                 |                   |             |           |
|-----------|-------------------|-----------------|-------------------|-------------|-----------|
| Location  | Doncaster         | Colour          | WHITE             | CAP Average | £4,000.00 |
| Reg. date | 12/05/2016        | VIN             | MPATFS86JFT027258 | CAP Below   | £2,875.00 |
| Year      | 2016              | Body Style      | Access Platform   | Gearbox     | MANUAL    |
| Mileage   | 106,724 Miles TBC | Service history | None              | Gears       | 6         |
| Fuel Type | DIESEL            | MOT Due         | 11/05/2027        | Axle Combi  | 4x4       |
| GVW       | 3500kg            | CAP Clean       | £4,875.00         |             |           |

\*LIFT ARM INOP - HYDRAULIC LEAK FROM THE LIFT ARM\* CPL A314 ACCESS PLATFORM

### Tyres





|       |  |
|-------|--|
| NSF   |  |
| NSR   |  |
| OSF   |  |
| OSR   |  |
| Spare |  |

## Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Park assist camera
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Scratched  
Rusted



2: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm



3: Sill os  
Chipped  
Multiple Chips



4: Door osf  
Scratched  
Over 25mm Thru Paint



5: Door osf  
Chipped  
Edge Chip



6: C Post ns  
Scratched  
Over 25mm Thru Paint



7: Door nsf  
Chipped  
Edge Chip



8: Door nsf  
Scratched  
Over 25mm Thru Paint



9: Wing nsf  
 Scratched  
 Over 25mm Not Thru Paint



10: Wing nsf  
 Scratched  
 Over 25mm Not Thru Paint



11: Bumper Front Moulding  
 Scuffed (Unpainted)  
 Over 100mm



12: Bumper Front Grill  
 Broken  
 Replace



13: Seat Base Cover osf  
 Torn  
 Over 3mm

**Interior**

| Carpet Condition         |    | Upholstery Condition                           |    |
|--------------------------|----|------------------------------------------------|----|
| Seat Condition           |    | Odour                                          |    |
| Engine Runs              | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes                   | OK | Clutch Slip Test from Static                   | OK |
| Turbo Boosting           | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake            | OK | No Excessive Smoking                           | OK |
| EML light illuminated    | OK | Oil warning light illuminated                  | OK |
| Airbag light illuminated | OK | DPF light illuminated                          | OK |
| ABS light illuminated    | OK | Service indicator light illuminated            | OK |
| Windows                  | OK | Radio                                          | OK |
|                          |    | Steering                                       | OK |