

VEHICLE INSPECTION REPORT

MK16HJN

VAUXHALL COMBO 2300 1.6 CDTI 16V 105ps H1

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present
		Cap Id	24261
		Cap Code	VACO16L235VDTM2 3 L

Details

Location	Doncaster	Colour	SILVER	CAP Average	£770.00
Reg. date	29/06/2016	VIN	W0L6WYD1BG9592691	CAP Below	£570.00
Year	2016	Body Style	Panel Van L2	Gearbox	MANUAL
Mileage	126,376 Miles Warranted	Service history	None	Gears	5
Fuel Type	DIESEL	MOT Due	08/05/2027		
GVW	2458kg	CAP Clean	£940.00		


Tyres



NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Rear parking sensor
- Digital radio
- Air conditioning
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Dented
Over 30mm



4: Door osr
Chipped
Multiple Chips




5: Bumper Rear
Scratched
Over 100mm Thru Paint



6: Qtr Panel osr
Dented
With Paint Damage



7: Wing osf
Dented
Over 30mm



8: Door osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		