

VEHICLE INSPECTION REPORT

LP68LCU

Mercedes-Benz Econic 2630

Non Runner **Serious Damage**

Inspection

Serious Damage? Yes

Vehicle

VAT Plus VAT
V5 Present
Cap Code 999900

Details

Location	Bedford	GVW	26000kg	Gearbox	AUTOMATIC
Reg. date	31/12/2018	Colour	ORANGE	Axle Combi	6x2
Year	2018	VIN	WDB9560332V255116	Rear Suspension	Air
Mileage	Not Showing	Body Style	Refuse Collector		
Fuel Type	DIESEL	Cab Type	CREW CAB		


NON RUNNER- GEARBOX & ENGINE REMOVED, ACCIDENT DAMAGED FAUN VARIOPRESS BODY, TERBERG SPLIT LIFT, MOT SHOWS 268,046KM 30/09/2026

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Photos





Condition Check



Damage Photos



1: Bumper Front
Missing
Replace



2: Fog Lamp Surround is
Broken
Replace



3: Door Qtr Light osf
Missing
Replace




4: Screen Front
Cracked
Replace



5: Grille Front
Broken
Replace



6: Number Plate Front
Missing
Replace



7: Door Qtr Light nsf
Missing
Replace



8: Bumper Front
Cracked
Over 25mm



9: Wing nsf
Cracked
Replace



10: Wing nsf
Scratched
Over 25mm Not Thru Paint



11: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Not Thru Paint



12: Fuel Flap
Missing
Replace



13: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



14: Lamp nsr
Missing
Replace



15: Fuel Flap
Missing
Replace



16: Wing Front Arch Extension os
Scratched (Painted)
Over 25mm Thru Paint



17: Door osf
Missing
Replace



18: Seat Base Cover osf
Holed
Over 3mm



19: Switches And Controls
Missing
Replace



20: Switches And Controls
Broken
Replace



21: Switches And Controls
Missing
Replace



22: Switches And Controls
Missing
Replace



23: Flasher Side Repeater os
Broken
Replace

Interior

Carpet Condition
Seat Condition

-
-

Upholstery Condition
Odour

-
-

Engine Runs Fault