

VEHICLE INSPECTION REPORT

SJ65GJE

Mercedes-Benz Antos 1827

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details


Reg. date	05/02/2016	VIN	WDB96300320015908	Axle Combi	4x2
Year	2016	Body Style	Fridge Box	Rear Suspension	Steel
Mileage	220,641 Km Warranted	MOT Due	30/11/2025	Rear Doors	Barn </td
Fuel Type	Diesel	Cab Type	DAY CAB	Tail Lift	Tuckaway
Colour	WHITE	Gearbox	AUTOMATIC		


FRIGOBLOCK FK24 UNIT

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Photos





Condition Check



Damage Photos



1: Fog Lamp Surround is
Broken
Replace



2: Screen Front
Chipped
Up To 10mm



3: Fog Lamp Surrounds
Scuffed (Unpainted)
Over 100mm



4: Bonnet
Chipped
Multiple Chips



5: Bumper Front
Dented
Over 30mm



6: General Exterior
Soiled
Light



7: General Exterior
Soiled
Light



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: General Exterior
Soiled
Light



10: General Exterior
Soiled
Light



11: General Exterior
Soiled
Light



12: General Exterior
Soiled
Light



13: General Exterior
Soiled
Light

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK