

# VEHICLE INSPECTION REPORT

**CP62UTL**

## Ford Ranger XL 2.2 TDCI 150PS

| Inspection      |    | Vehicle  |                    |
|-----------------|----|----------|--------------------|
| Serious Damage? | No | VAT      | Plus VAT           |
|                 |    | V5       | Present            |
|                 |    | Cap Id   | 22413              |
|                 |    | Cap Code | FORA22XL 7DTM4 4 L |

### Details

|           |                            |             |                   |            |         |
|-----------|----------------------------|-------------|-------------------|------------|---------|
| Location  | Doncaster                  | Colour      | SILVER            | CAP Below  | £725.00 |
| Reg. date | 27/02/2013                 | VIN         | 6FPGXXMJ2GCS78365 | Gearbox    | MANUAL  |
| Year      | 2013                       | Body Style  | Pickup Double Cab | Gears      | 6       |
| Mileage   | 169,132 Miles<br>Warranted | MOT Due     | 25/10/2026        | Axle Combi | 4x4     |
| Fuel Type | DIESEL                     | CAP Clean   | £1,525.00         |            |         |
| GVW       | 3200kg                     | CAP Average | £1,150.00         |            |         |

\*COLLECTED AS NON-RUNNER - UNKNOWN FAULTS RECOMMENDED NOT TO DRIVE, WARNING LIGHTS ON DASH\* E/ MIRRORS

### Tyres




|       |
|-------|
| NSF   |
| NSR   |
| OSF   |
| OSR   |
| Spare |

## Features

- Radio/CD
- Passenger airbag
- Air conditioning
- Central locking
- Front electric windows
- Cloth seat trim
- Drivers airbag


## Photos







## Condition Check



## Damage Photos



1: Wing of  
Scratched  
Over 25mm Thru Paint




2: Bonnet  
Chipped  
Multiple Chips




3: Bumper Front  
Scratched  
Over 100mm Thru Paint




4: Wing nsf  
Dented  
With Paint Damage




5: Door Mirror Assy nsf  
Broken  
Replace



6: Door nsf  
Dented  
With Paint Damage



7: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



8: Qtr Panel nsr  
Dented  
With Paint Damage



9: Qtr Panel nsr  
Dented  
With Paint Damage



10: Qtr Panel nsr  
Rusted  
Holed




11: Panel Rear  
Rusted  
Holed



12: Qtr Panel osr  
Rusted  
Holed



13: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



14: Seat Base Cover nsr  
Soiled  
Heavy



15: Seat Base Cover osr  
Soiled  
Heavy



16: Seat Base Cover osf  
Holed  
Over 3mm



17: Dash Warning Lights  
Displayed  
No Action



18: Screen Front  
Chipped  
Over 10mm

Interior

|                         |      |                                     |       |
|-------------------------|------|-------------------------------------|-------|
| <b>Carpet Condition</b> | OK   | <b>Upholstery Condition</b>         | OK    |
| <b>Seat Condition</b>   | Poor | <b>Odour</b>                        | No    |
| Engine Runs             | OK   | No Excessive Smoking                | OK    |
| EML light illuminated   | OK   | DPF light illuminated               | OK    |
| ABS light illuminated   | OK   | Service indicator light illuminated | Fault |