

VEHICLE INSPECTION REPORT

WX20KJN

Fiat Ducato 35 2.3 MULTIJET 140PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow
		Cap Id	44846
		Cap Code	FIDU233MM4HDTM2 5 L

Details

Location	Doncaster	GVW	3500kg	CAP Clean	£6,775.00
Reg. date	29/06/2020	Colour	WHITE	CAP Average	£5,925.00
Year	2020	VIN	ZFA25000002N87870	CAP Below	£4,775.00
Mileage	76,790 Miles Warranted	Body Style	Panel Van MWB	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	20/05/2027	Gears	6


AD BLUE, SIDE LOADING DOOR, E/MIRRORS


Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Front parking sensor
- Navigation system
- Rear parking sensor
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



2: Screen Front
Chipped
Over 10mm



3: Bonnet
Chipped
Multiple Chips



4: Wing nsf
Dented
With Paint Damage



5: Door nsf
Dented
Over 2 UpTo 10mm



6: Qtr Panel Trim ns
Missing
Replace



7: Door nsr
Dented
Over 2 UpTo 10mm



8: Door osf
Chipped
Edge Chip



9: Carpets Front
 Holed
 Over 3mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Average	Odour	Average No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK