

VEHICLE INSPECTION REPORT

YA66VCJ

Daf LF 150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 01/02/2017

VIN XLRAEL1500L459023

Axle Combi 4x2

Year 2017

Body Style Box Van

Rear Suspension Steel

Mileage 268,499 Km Warranted

MOT Due 31/10/2025

Rear Doors Roller

Fuel Type Diesel

Cab Type DAY CAB

Tail Lift Column

Colour SILVER

Gearbox MANUAL

HALF CURTAINSIDE, BEEN ON FULL R & M CONTRACT FROM NEW

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4

OSO1 OSO2 OSO3 OSO4

Features


- Park assist camera

Photos





Condition Check



Damage Photos



1: Moulding on Wing
Scratched (Painted)
Over 25mm Thru Paint



2: Bumper Front
Dented
Over 30mm



3: Screen Front
Chipped
Over 10mm



4: Moulding nsf Wing
Scratched (Painted)
Over 25mm Thru Paint



5: Bumper Front
Scratched
Over 25mm Not Thru Paint



6: General Exterior
Soiled
Light



7: Door Mirror Glass ns
Broken
Replace



8: Qtr Panel osr
Scratched
Over 25mm Thru Paint



9: Qtr Panel osr
Scratched
Over 25mm Thru Paint



10: General Exterior
Soiled
Light



11: General Exterior
Soiled
Light



12: Seat Base Cover osf
Torn
Over 3mm



13: Other
N/A
N/A

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	