

## VEHICLE INSPECTION REPORT

**DN73HVL**

### Vauxhall Vivaro 2900 1.5d 100PS Prime

| Inspection      |    | Vehicle  |                     |
|-----------------|----|----------|---------------------|
| Serious Damage? | No | VAT      | Plus VAT            |
|                 |    | V5       | Present             |
|                 |    | Cap Id   | 56177               |
|                 |    | Cap Code | VAVI1519P1VDTM2 3 L |

#### Details

|           |                            |            |                   |             |            |
|-----------|----------------------------|------------|-------------------|-------------|------------|
| Location  | Livingston                 | GVW        | 2900kg            | CAP Clean   | £11,150.00 |
| Reg. date | 31/10/2023                 | Colour     | WHITE             | CAP Average | £10,350.00 |
| Year      | 2023                       | VIN        | VXEVBVHRMP7865373 | CAP Below   | £8,875.00  |
| Mileage   | 31,181 Miles Not Warranted | Body Style | Panel Van L1      | Gearbox     | MANUAL     |
| Fuel Type | DIESEL                     | MOT Due    | 30/10/2026        | Gears       | 6          |

\*WARNING LIGHT ON DASH\* E/MIRRORS

#### Tyres

NSF

NSR

OSF


OSR



Spare

### Features


- Rear parking sensor
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking

### Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Panel Front  
Chipped  
Multiple Chips



3: Qtr Panel osr  
Dented  
Over 30mm



4: Tailgate  
Dented  
Over 30mm



5: Qtr Panel nsr  
Dented  
Over 30mm



6: Panel Rear  
Scratched  
Over 25mm Thru Paint

**Interior**

| Carpet Condition         |       | Average |  | Upholstery Condition                           |       | Average |  |
|--------------------------|-------|---------|--|------------------------------------------------|-------|---------|--|
| Seat Condition           |       | Average |  | Odour                                          |       | No      |  |
| Engine Runs              | OK    |         |  | Gearbox 1st and Reverse Test                   | OK    |         |  |
| Brakes                   | OK    |         |  | Clutch Slip Test from Static                   | OK    |         |  |
| Turbo Boosting           | OK    |         |  | Gearbox Static Gear Selection (engine running) | OK    |         |  |
| Parking Brake            | OK    |         |  | No Excessive Smoking                           | OK    |         |  |
| EML light illuminated    | Fault |         |  | Oil warning light illuminated                  | OK    |         |  |
| Airbag light illuminated | OK    |         |  | DPF light illuminated                          | OK    |         |  |
| ABS light illuminated    | OK    |         |  | Service indicator light illuminated            | Fault |         |  |