

# VEHICLE INSPECTION REPORT

**AU20LTY**

## Renault Master

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 27/05/2020

Year 2020

Mileage 48,793 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN VF6VF000964693455

Body Style Access Platform

Service history Yes

MOT Due 01/02/2026

Cab Type DAY CAB

Gearbox MANUAL

Rear Suspension Steel

\*WARNING LIGHTS ON DASH\* MILEAGE INPUT ERROR ON MOT, KLUBB K38P PLATFORM

### Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Park assist camera
- Air conditioning


## Photos







## Condition Check



## Damage Photos



1: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



2: Screen Front  
Chipped  
UpTo 10mm



3: Bonnet  
Chipped  
Multiple Chips



4: Bumper Front  
Dented  
Over 30mm



5: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



6: Wheel nsf  
Dented  
Over 30mm (Steel)



7: Door nsf  
Chipped  
Edge Chip



8: Door nsr  
Cracked  
Replace





9: Bumper Rear  
Dented  
With Paint Damage



10: Door nsr  
Dented  
Over 30mm



11: Qtr Panel osr  
Dented  
Over 30mm



12: Door osf  
Dented  
Over 2 UpTo 10mm



13: Door Mirror Assy osf  
Broken  
Replace



14: General Exterior  
Soiled  
Light



15: Other  
N/A  
N/A

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	Fault		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	Fault