

VEHICLE INSPECTION REPORT

BG18UBK

Nissan Navara Tekna 2.3dCi 190PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply
		Cap Id	39510
		Cap Code	NINA23TEK 7DTM4 4 L

Details

Location	Doncaster	Colour	BLACK	CAP Below	£3,175.00
Reg. date	30/03/2018	VIN	VSKCTND23U0079952	Gearbox	MANUAL
Year	2018	Body Style	Pickup Double Cab	Gears	6
Mileage	225,811 Miles Not Warranted	MOT Due	06/04/2027	Axle Combi	4x4
Fuel Type	DIESEL	CAP Clean	£4,950.00		
GVW	3045kg	CAP Average	£4,200.00		

WARNING LIGHTS ON DASH TOW BAR, E/MIRRORS, AD-BLUE

Tyres







NSF	
NSR	
OSF	
OSR	
Spare	



Features

- Bluetooth connection
- Park assist camera
- Radio/CD
- Metallic Paint
- Leather seat trim
- Cruise control
- Rear parking sensor
- Air conditioning
- Drivers airbag
- Heated front seat
- Auxiliary input socket
- Front electric windows
- Passenger airbag
- Navigation system
- Digital radio
- Rear electric windows
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Insecure
Action Required



3: Wing nsf
Poor Previous Repair
Poor Paint



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



9: Qtr Panel nsr
Dented
Over 30mm



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



12: Tailgate
Scratched
Over 25mm Thru Paint



13: Tailgate Trim Panel
Broken
Replace



14: Qtr Panel osr
Dented
With Paint Damage



15: Qtr Panel osr
Scratched
Over 25mm Thru Paint



16: Qtr Panel osr
Dented
With Paint Damage



17: Door osr
Chipped
Multiple Chips



18: Door osf
Chipped
Multiple Chips



19: Wing osf
Scratched
Over 25mm Thru Paint



20: Screen Front
Chipped
Over 10mm



21: Seat Base Cover osf
Torn
Over 3mm



22: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		Poor	Odour		No
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		Fault	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		Fault