

# **VEHICLE INSPECTION REPORT**

PF19TZZ

# **Daf CF 410**

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	Present		
Details					
Reg. date	14/06/2019	VIN	XLRACM4100G246669	Axle Combi	8x2
Year	2019	Body Style	Beavertail	Steering Combi	Rear-Lift Steer
Mileage	319,579 Km Warranted	MOT Due	31/08/2025	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	DAY CAB		
Colour	WHITE	Gearbox	AUTOMATIC		

### CHEESE WEDGE, FLIP RAMP, SURROUND CAMERA SYSTEM, WINCH

#### **Tyres**

NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NSO1	NSO2	NSO3	NSO4	
	OSO1	OSO2	oso3	OSO4	

## **Features**

Park assist camera

• Air conditioning

### **Photos**

















# **Condition Check**



# **Damage Photos**



1: Fog Lamp Surround os Scratched (Painted) Over 25mm Thru Paint



2: Bonnet Scratched Over 25mm Thru Paint



3: Door nsf Dented Over 2 UpTo 10mm



4: Door Mirror Assy nsf Scuffed (Unpainted) Over 100mm



5: Wing Front Arch Extension ns Scuffed (Unpainted) Over 100mm



6: Door osf Dented Over 2 UpTo 10mm



7: Wing Front Arch Extension os Scuffed (Unpainted) Over 100mm



8: Carpets Front Holed Over 3mm



9: Seat Base Cover osf Torn Over 3mm

### Interior

Carpet Condition Seat Condition	Average Average		Upholstery Condition Average Odour -	
Engine Runs		OK	Gearbox 1st and Reverse Test	OK
Brakes		OK	Clutch Slip Test from Static	OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated		OK	Oil warning light illuminated	OK
Airbag light illuminated	l	OK	DPF light illuminated	OK
ABS light illuminated		OK	Service indicator light illuminated	OK