

VEHICLE INSPECTION REPORT

BD64DTK

Iveco Daily 50C15

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	28/10/2014	VIN	ZCFC50A400D522629	Gears	6
Year	2014	Body Style	Access Platform	Brakes	Drum
Mileage	237,434 Km Warranted	Service history	Yes	Axle Combi	4x2
Fuel Type	Diesel	Service documents	Electronic / Online	Rear Suspension	Steel
Colour	WHITE	Gearbox	MANUAL	Rear Doors	Barn

VERSALIFT EUROTREL 38LF (YOM 2013)

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Front electric windows
- Drivers airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Bonnet
Dented
With Paint Damage



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



4: Door osf
Rusted
Over 5mm



5: Qtr Panel osr
Rusted
Over 5mm



6: Door nsr
Dented
With Paint Damage



7: Door nsf
Rusted
Over 5mm



8: Flasher Side Repeater ns
Broken
Replace

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Average	Odour	Average -
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	Fault	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK