

VEHICLE INSPECTION REPORT



Volvo B9R PLAXTON PANTHER

| Inspection | | Vehicle | | |
|--------------------|----|---------|-----------|--|
| Serious Damage? No | | AT | Plus VAT | |
| | V5 | 5 | To Follow | |

| Details | | | | | |
|-----------|----------------------|------------|------------|-----------------|-----------|
| Reg. date | 22/04/2013 | Colour | WHITE | Gearbox | AUTOMATIC |
| Year | 2013 | VIN | | Axle Combi | 4x2 |
| Mileage | 214,892 Km Warranted | Body Style | Coach | Rear Suspension | Air |
| Fuel Type | DIESEL | MOT Due | 14/11/2025 | | |

5% BUYERS FEE 53 SEATS + DRIVER, KNEEL FUNCTION, FABRIC RECLINING SEATS WITH FOOT RESTS, 3PT SEATBELT, OVERHEAD STOWAGE, REAR EMERGENCY EXIT

| Tyres | | | | | |
|-------|------|------|------|------|--|
| NSF | NSI1 | NSI2 | NSI3 | NSI4 | |
| OSF | OSI1 | OSI2 | OSI3 | OSI4 | |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 | |
| | OS01 | OSO2 | OSO3 | OSO4 | |

Features

| Bluetooth connection | Cruise control | Digital radio | Radio/CD |
|--------------------------------------|--|-------------------------------------|----------|
| Air conditioning | Front electric windows | Cloth seat trim | |

Photos








































Condition Check



Damage Photos



1: Bonnet Scratched Over 25mm Not Thru Paint

2: Qtr Panel nsr Dented Over 30mm






3: Qtr Panel nsr Dented Over 30mm



5: Boot Lid Cracked Replace





6: Carpets Front Soiled Heavy



7: Carpets Rear Soiled Heavy

Interior



8: Seat Base Cover osr Torn Over 3mm

| Carpet Condition Seat Condition | Poor Poor | | Upholstery Condition Odour | ОК - | |
|------------------------------------|--------------|----|-------------------------------|---------|----|
| Engine Runs | | OK | No Excessive Smoking | | OK |
| EML light illuminated | | OK | DPF light illuminated | | OK |
| ABS light illuminated | | OK | | | |