

VEHICLE INSPECTION REPORT

EF67KUK

Mercedes-Benz Sprinter 314 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 30/11/2017

Year 2017

Mileage 53,728 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN WDB9066332P555426

Body Style Welfare Unit

MOT Due Expired

CAP Clean £6,000.00

CAP Average £5,075.00

CAP Below £3,850.00

Gearbox AUTOMATIC

SINGLE SIDE DOOR, AD BLUE

Tyres

NSF

NSR

OSF

OSR



Spare

Features


- Rear parking sensor
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Screen Front
Chipped
Over 10mm



3: Door nsr
Scratched
Over 25mm Not Thru Paint



4: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



5: Qtr Panel osr
Cracked
Replace



6: Sill os
Dented
Over 30mm



7: Door osf
Dented
Over 2 UpTo 10mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK