

VEHICLE INSPECTION REPORT

PO18SCV

Daf CF 460

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow
		Cap Code	999900

Details

Location	Livingston	GVW	32000kg	Cab Type	DAY CAB
Reg. date	17/07/2018	Colour	RED	Gearbox	AUTOMATIC
Year	2018	VIN	XLRACM4300G181631	Axle Combi	8x2
Mileage	379,292 Km Warranted	Body Style	Beavertail & Crane	Rear Suspension	Air
Fuel Type	DIESEL	MOT Due	30/04/2027		

REAR RAMPS INOP HIAB 422EP- 4 HIDUO REMOTE CRANE (YEAR 2017), CHEESE WEDGE RAMPS, RAMSEY WINCH, REAR LIFT.


Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Radio/CD
- Air conditioning


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Qtr Panel Moulding os
Scratched (Painted)
Over 25mm Thru Paint



3: Door osf
Chipped
Multiple Chips



4: Qtr Panel osr
Rusted
Over 5mm



5: Tailgate
Rusted
Over 5mm



6: Qtr Panel nsr
Rusted
Over 5mm



7: Other
N/A
N/A



8: Qtr Panel Moulding ns
Scratched (Painted)
Over 25mm Thru Paint

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs		OK		Gearbox 1st and Reverse Test		OK	
Brakes		OK		Clutch Slip Test from Static		OK	
Turbo Boosting		OK		Gearbox Static Gear Selection (engine running)		OK	
Parking Brake		OK		No Excessive Smoking		OK	
EML light illuminated		OK		Oil warning light illuminated		OK	
Airbag light illuminated		OK		DPF light illuminated		OK	
ABS light illuminated		OK		Service indicator light illuminated		OK	