

VEHICLE INSPECTION REPORT

EJ71AUP

Ford Transit Custom 300 2.0 ECOBLUE 130PS LEADER

Inspection

Serious Damage? No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	44503
Cap Code	FOTU200L3LHDTM2 1 L

Details

Location	Bedford	GVW	3000kg	CAP Clean	£5,775.00
Reg. date	23/12/2021	Colour	WHITE	CAP Average	£5,150.00
Year	2021	VIN	WF0YXXTTGYMG49265	CAP Below	£4,225.00
Mileage	120,874 Miles Not Warranted	Body Style	Fridge Van L2	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	22/12/2026	Gears	6

WARNING LIGHT ON DASH, WINDSCREEN CRACKED GAH UNIT, AD BLUE, SIDE LOADING DOOR

Tyres

NSF

NSR

OSF

OSR

Spare




Features

• Air conditioning


• Front electric windows

Photos





Condition Check




Damage Photos



1: Bumper Front
Scratched
UpTo 25mm Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Screen Front
Cracked
Replace



4: Roof
Rusted
Over 5mm



5: Bumper Front
Scratched
Over 25mm Not Thru Paint



6: Bonnet
Dented
Between 10mm + 30mm



7: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



8: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



9: Qtr Panel Trim ns
Missing
Replace



10: Door nsr
Dented
With Paint Damage



11: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



12: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



13: Door nsr
Dented
Between 10mm + 30mm



14: Door nsr
Dented
Between 10mm + 30mm



15: Door osr
Dented
Between 10mm + 30mm



16: Door osr
Scratched
Over 25mm Not Thru Paint



17: Qtr Panel osr
Dented
With Paint Damage



18: Qtr Panel osr
Scratched
Over 25mm Thru Paint



19: Door osf
Chipped
Edge Chip

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK