

VEHICLE INSPECTION REPORT

PG66UFB

DAF CF 440

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Cap Code 999900

Details

Location Bedford

Reg. date 27/02/2017

Year 2017

Mileage 1,205,166 Km
Warranted

Fuel Type DIESEL

GVW 44000kg

Colour RED

VIN XLRTGM4100G148330

Body Style Tractor Unit

Service history Yes

MOT Due 30/04/2027

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

AD BLUE

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3


OSO4

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Wing of
Chipped
Multiple Chips



2: Bonnet
Chipped
Multiple Chips



3: Fog Lamp Surround os
Scratched (Painted)
UpTo 25mm Thru Paint



4: Bumper Front
Chipped
Multiple Chips



5: Bumper Front
Dented
With Paint Damage



6: Wing nsf
Cracked
Replace



7: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



8: Door nsf
Dented
Over 30mm



9: Door nsf
Scratched
UpTo 25mm Thru Paint



10: Wing Front Arch Extension os
Scuffed (Unpainted)
UpTo 100mm



11: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



12: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Average	Odour	Average -
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK