



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PK23YNL

Volvo FH 500

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Cap Code 999900

Details

Location Avonmouth

Reg. date 09/06/2023

Year 2023

Mileage 272,935 Km Not Warranted

Fuel Type DIESEL

GVW 44000kg

Colour BLACK

VIN YV2RT40C4PB432370

Body Style Tractor Unit

MOT Due 31/01/2027

Cab Type GLOBETROTTER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

WEIGH SYSTEM, SURROUND CAMERA SYSTEM

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4



Spare NSO1 NSO2 NSO3 NSO4






OSO1 OSO2 OSO3 OSO4



Features

- Bluetooth connection
- Digital radio
- Front electric windows
- Cruise control
- Mobile phone App interface
- Drivers airbag
- Navigation system
- USB/iPod interface
- Central locking
- Auxiliary input socket
- Air conditioning
- Partial leather seat trim

Photos










Condition Check



Damage Photos



1: Wing nsf
Scratched
Over 25mm Thru Paint



2: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



3: Door nsf
Scratched
UpTo 25mm Thru Paint



4: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



5: Wheel nsf
Corroded
Light



6: Wheel nsr
Corroded
Light




7: Wheel osr
Corroded
Light



8: Wheel osf
Corroded
Light



9: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



10: Fuel Flap
Missing
Replace



11: Door osf
Scratched
Over 25mm Not Thru Paint



12: Door Mirror Assy osf
Missing
Replace



13: Wing osf
Dented
Over 30mm



14: Wing osf
Scratched
Over 25mm Thru Paint



15: Bumper Front
Hole
Over 25mm

16: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Turbo Boosting	OK			Gearbox Static Gear Selection (engine running)	OK		
Parking Brake	OK			No Excessive Smoking	OK		
EML light illuminated	OK			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	OK		
ABS light illuminated	OK			Service indicator light illuminated	OK		
Windows	OK			Radio	OK		
Sat nav	OK						