



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PN20EUA

Volvo FH 500

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Cap Code 999900

Details

Location	Avonmouth	GVW	44000kg	Cab Type	GLOBETROTTER CAB
Reg. date	01/03/2020	Colour	BLACK	Gearbox	AUTOMATIC
Year	2020	VIN	YV2RT40C4LB305953	Axle Combi	6x2
Mileage	546,255 Km Not Warranted	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Fuel Type	DIESEL	MOT Due	31/01/2027	Rear Suspension	Air

WEIGH SYSTEM, SURROUND CAMERA SYSTEM


Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- USB/iPod interface
- Central locking
- Cruise control
- Air conditioning
- Partial leather seat trim
- Auxiliary input socket
- Front electric windows
- Radio/CD
- Drivers airbag

Photos





Department for Transport		Vehicle Identification No.		Serial No.	
Driver & Vehicle Standards Agency	Plate	Vehicle Identification No.	Variant	Serial No.	199901417288
Reg. from: M63	PN20EUA	YY2RT40C4LB30553	Variant	199901417288	090717
Type Approval No. VOLVO FH					
Manufacturer Model					
Year of Original Registration 01/03/20					
Year of Manufacture 2020					
Description of Weights Applicable to Vehicle					
Gross Weight (kg) 22800 24000 24000					
Train Weight (kg) 44000 40000					
Max Train Weight (kg) 44000 44000					
Date of issue 03/03/20					
DEPARTMENT FOR TRANSPORT GREAT BRITAIN					
REPLACEMENT					
Type use conversion applicable to vehicle 20					

Volvo Truck Corporation			
Drive			
WB			
Product type			Kg
1			Kg
2			Kg
3			Kg
4			Kg
5			Kg



VOLVO	
VU2RT40C4LB30553	
L	m
W	m
a	m
a min	m
a max	m




VOLVO	
Cab type	FH
Approval number	
Serial number	6016285
Process colour	C 1723







Condition Check



Damage Photos



1: Panel Front
Missing
Replace



2: Panel Front
Dented
Over 30mm



3: Grille Front
Broken
Replace



4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Door Mirror Assy nsf
Broken
Replace



6: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



7: Wheel nsf
Corroded
Light



8: Wheel nsr
Corroded
Light



9: Wheel osr
Corroded
Light



10: Qtr Panel osr
Cracked
Replace



11: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



12: Wheel osf
Corroded
Light



13: Qtr Panel osr
Chipped
Over 5mm



14: Door osf
Chipped
Edge Chip



15: Door osf
Dented
Over 30mm



16: Door osf
Scratched
Over 25mm Thru Paint



17: Door osf
Chipped
Over 5mm



18: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



19: Wing osf
Scratched
Over 25mm Thru Paint



20: Bumper Front
Scratched
Over 100mm Thru Paint



21: Seat Back Cover osf
Torn
Over 3mm



22: Air Vents osf
Damaged
Replace

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Turbo Boosting	OK			Gearbox Static Gear Selection (engine running)	OK		
Parking Brake	OK			No Excessive Smoking	OK		
EML light illuminated	OK			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	OK		
ABS light illuminated	OK			Service indicator light illuminated	OK		
Windows	OK			Radio	OK		