



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PN21KKV

Volvo FH 500

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Cap Code 999900

Details

Location Avonmouth

Reg. date 01/03/2021

Year 2021

Mileage 462,461 Km Not Warranted

Fuel Type DIESEL

GVW 44000kg

Colour BLACK

VIN YV2RT40C6MB333027

Body Style Tractor Unit

MOT Due 31/01/2027

Cab Type GLOBETROTTER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

WARNING LIGHTS ON DASH, SURROUND CAMERA SYSYTEM

Tyres

NSF

NSI1

NSI2

NSI3

NSI4

OSF

OSI1

OSI2

OSI3

OSI4

Spare

NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3

OSO4

Features

- Bluetooth connection
- Digital radio
- Front electric windows
- Cruise control
- Radio/CD
- Drivers airbag
- Park assist camera
- USB/iPod interface
- Central locking
- Auxiliary input socket
- Air conditioning
- Partial leather seat trim

Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Panel Front
Chipped
Over 5mm




3: Wing nsf
Chipped
Over 5mm



4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsf
Dented
Over 30mm



7: Door Mirror Assy nsf
Broken
Replace



8: Wheel nsf
Corroded
Light



9: Wheel nsr
Corroded
Light



10: Wheel osr
Corroded
Light



11: Wheel osf
Corroded
Light



12: Qtr Panel osr
Chipped
Over 5mm



13: Door osf
Chipped
Edge Chip



14: Door osf
Chipped
Over 5mm



15: Door osf
Dented
Over 30mm



16: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



17: Wing Front Arch Extension os
Scratched (Painted)
Over 25mm Thru Paint



18: Bumper Front
Scratched
Over 100mm Thru Paint



19: Panel Front
Chipped
Over 5mm



20: Handle Inner osf
Damaged
Replace



21: Seat Base Cover osf
Torn
Over 3mm

22: Handle Outer osf
Scratched (Painted)
Over 25mm Thru Paint

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Parking Brake	OK			Gearbox Static Gear Selection (engine running)	OK		
				No Excessive Smoking	OK		
EML light illuminated	Fault			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	OK		
ABS light illuminated	OK			Service indicator light illuminated	OK		
Windows	OK			Radio	OK		