

VEHICLE INSPECTION REPORT

CN19WDK

Mercedes-Benz Sprinter 314 CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present
		Cap Id	42949
		Cap Code	MESP2134LFVDTM2 5 L

Details

Location	Doncaster	VIN	WDB9106312P077144	CAP Clean	£7,000.00
Reg. date	15/07/2019	Body Style	Panel Van L1	CAP Average	£6,075.00
Year	2019	Service history	Yes	CAP Below	£4,725.00
Mileage	173,939 Miles Warranted	Service documents	Printout	Gearbox	MANUAL
Fuel Type	DIESEL	Number of stamps	5	Gears	6
GVW	3500kg	Last service date	13/11/2025		
Colour	WHITE	MOT Due	15/07/2027		

REAR DOOR INOP, E/MIRRORS, AD-BLUE

Tyres

NSF

NSR

OSF

OSR




Spare

Features

- Bluetooth connection
- Digital radio
- Central locking
- Cruise control
- Air conditioning
- Cloth seat trim
- Front parking sensor
- Front electric windows
- Rear parking sensor
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Other
N/A
N/A
Sld does not close



4: Qtr Panel nsr
Dented
With Paint Damage



5: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



6: Door nsr
Chipped
Multiple Chips



7: Door osr
Dented
With Paint Damage



8: Door osr
Dented
Over 30mm



9: Door osr
Dented
With Paint Damage



10: Qtr Panel osr
Rusted
Over 5mm



11: B Post os
Rusted
Over 5mm



12: Door osf
Chipped
Multiple Chips



13: Door osf
Dented
With Paint Damage



14: Wing osf
Dented
Over 30mm



15: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK