



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PJ22GME

Volvo FH 500

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Cap Code 999900

Details

Location Avonmouth

Reg. date 01/06/2022

Year 2022

Mileage 363,485 Km Not Warranted

Fuel Type DIESEL

GVW 44000kg

Colour BLACK

VIN YV2RT40C1NA302131

Body Style Tractor Unit

MOT Due 28/02/2027

Cab Type GLOBETROTTER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

SURROUND CAMERA SYSTEM

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4


Spare NSO1 NSO2 NSO3 NSO4







OSO1 OSO2 OSO3 OSO4


Features

- Bluetooth connection
- Digital radio
- Front electric windows
- Cruise control
- Mobile phone App interface
- Drivers airbag
- Navigation system
- USB/iPod interface
- Central locking
- Auxiliary input socket
- Air conditioning
- Partial leather seat trim

Photos










Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Panel Front
Chipped
Over 5mm



3: Wing nsf
Chipped
Over 5mm



4: Wing nsf
Cracked
Replace



5: Door nsf
Dented
Over 30mm



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Wheel nsf
Corroded
Light



8: Door nsf
Chipped
Over 5mm



9: Bumper Front
Cracked
Over 25mm



10: Wheel nsr
Corroded
Light



11: Wheel osr
Corroded
Light



12: Fuel Flap
Missing
Replace



13: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



14: Wheel osf
Corroded
Light



15: Qtr Panel osf
Chipped
Over 5mm



16: Door osf
Chipped
Edge Chip



17: Door osf
Chipped
Over 5mm



18: Door osf
Dented
Over 30mm



19: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



20: Wing osf
Chipped
Over 5mm



21: Bumper Front
Cracked
Over 25mm



22: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



23: Door nsf
Dented
Over 30mm



24: Switches And Controls
Broken
Replace



25: Centre Console Front
Holed
Over 3mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Turbo Boosting		OK	Gearbox Static Gear Selection (engine running)		OK
Parking Brake		OK	No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK
Windows		OK	Radio		OK
Sat nav		OK			