

# VEHICLE INSPECTION REPORT

**DX20UKT**

## Daf XF 450

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

Cap Code 999900

### Details

Location Avonmouth

Reg. date 01/03/2020

Year 2020

Mileage 468,289 Km Not Warranted

Fuel Type DIESEL

GVW 44000kg

Colour BLACK

VIN XLRTGH4100G303293

Body Style Tractor Unit

MOT Due Expired

Cab Type SPACE CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

### \*WARNING LIGHTS ON DASH\*



#### Tyres



| NSF   | NSI1 | NSI2 | NSI3 | NSI4 |
|-------|------|------|------|------|
| OSF   | OSI1 | OSI2 | OSI3 | OSI4 |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 |
|       | OSO1 | OSO2 | OSO3 | OSO4 |


## Features

- Bluetooth connection
- Cruise control
- Digital radio
- Air conditioning
- Front electric windows
- Drivers airbag
- Central locking
- Cloth seat trim


## Photos







## Condition Check



## Damage Photos



1: Screen Front  
Chipped  
Over 10mm



2: Panel Front  
Chipped  
Over 5mm



3: Wing nsf  
Cracked  
Replace



4: Bumper Front  
Scratched  
Over 100mm Thru Paint



5: Fog Lamp Surround ns  
Scratched (Painted)  
Over 25mm Thru Paint




6: Door nsf  
Scratched  
Over 25mm Thru Paint



7: Door Mirror Assy nsf  
Scuffed (Unpainted)  
Over 100mm



8: Wing Front Arch Extension ns  
Scratched (Painted)  
Over 25mm Thru Paint



9: Qtr Panel Arch Extension ns  
Scratched (Painted)  
Over 25mm Thru Paint



10: Wheel nsf  
Corroded  
Light



11: Door nsf  
Chipped  
Edge Chip



12: Qtr Panel nsr  
Chipped  
Over 5mm



13: Wheel nsr  
Corroded  
Light



14: Qtr Panel Arch Extension ns  
Scuffed (Unpainted)  
Over 100mm



15: Qtr Panel Arch Extension os  
Scuffed (Unpainted)  
Over 100mm



16: Wheel osr  
Corroded  
Light



17: Qtr Panel osr  
Chipped  
Over 5mm



18: Wing Front Arch Extension os  
Scratched (Painted)  
Over 25mm Thru Paint



19: Wheel osf  
Corroded  
Light



20: Door osf  
Chipped  
Edge Chip



21: Door osf  
Chipped  
Over 5mm



22: Wing Front Arch Extension os  
Broken  
Replace



23: Door Mirror Assy osf  
Scuffed (Unpainted)  
Over 100mm



24: Wing osf  
Cracked  
Replace




25: Bumper Front  
Chipped  
Over 5mm




26: Bumper Front  
Chipped  
Over 5mm



27: Grille Front  
Broken  
Replace



28: Seat Base Cover osf  
Torn  
Over 3mm



29: Switches And Controls  
Missing  
Replace



30: Seat Base Cover nsf  
Torn  
Over 3mm

## Interior

| Carpet Condition         |       | Average |  | Upholstery Condition                           |       | Average |  |
|--------------------------|-------|---------|--|------------------------------------------------|-------|---------|--|
| Seat Condition           |       | Average |  | Odour                                          |       | -       |  |
| Engine Runs              | OK    |         |  | Gearbox 1st and Reverse Test                   | OK    |         |  |
| Brakes                   | OK    |         |  | Clutch Slip Test from Static                   | OK    |         |  |
| Parking Brake            | OK    |         |  | Gearbox Static Gear Selection (engine running) | OK    |         |  |
|                          |       |         |  | No Excessive Smoking                           | OK    |         |  |
| EML light illuminated    | Fault |         |  | Oil warning light illuminated                  | OK    |         |  |
| Airbag light illuminated | OK    |         |  | DPF light illuminated                          | Fault |         |  |
| ABS light illuminated    | Fault |         |  | Service indicator light illuminated            | OK    |         |  |
| Windows                  | OK    |         |  | Radio                                          | OK    |         |  |

