

VEHICLE INSPECTION REPORT



Mercedes-Benz Sprinter 3.5t Progressive

Inspection	Vehicle	
Serious Damage? No	VAT	Plus VAT
	V5	Present

Details

Reg. date	27/04/2023	VIN	W1V9071352N197633	CAP Below	£20,400.00
Year	2023	Body Style	Luton L3	Gearbox	MANUAL
Mileage	16,920 Miles Not	MOT Due	26/04/2026	Tail Lift	Column
	Warranted	CAP Clean	£24,700.00		
Fuel Type	Diesel	CAP Average	£23.250.00		
Colour	WHITE				

WARNING LIGHTS ON DASH AD-BLUE

Tyres			
Tyres NSF			
NSR			
OSF			
OSR			
Spare			

Features

Bluetooth connection

Drivers airbag

Cruise control

- Passenger airbag
- Digital radioCentral locking
- Front electric windows
- Cloth seat trim

Photos

































Condition Check



Damage Photos





1: Bumper Front Dented With Paint Damage

2: Door Mirror Assy nsf Scuffed (Unpainted) Over 100mm





3: Qtr Panel nsr Scratched Over 25mm Thru Paint



4: Qtr Panel osr Scratched Over 25mm Thru Paint

5: Seat Base Cover nsf Soiled Heavy

Interior

Carpet Condition Seat Condition	OK Poor		Upholstery Condition Odour	OK No	
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		ОК	DPF light illuminated		OK
ABS light illuminated		OK			