

VEHICLE INSPECTION REPORT

GM19VNJ

Daf CF 260

Inspection		Vehicle			
Serious Damage?	No	VAT Plus VAT			
		V5	Buyer To Apply		
Details					
Reg. date	14/06/2019	VIN	XLRAEM3700G26	2556 Axle Co	ombi 4x2
Year	2019	Body Style	Curtainside	Rear Su	ispension Air
Mileage	577,084 Km Not	MOT Due	31/03/2026	Rear Do	oors Barn
	Warranted	Cab Type	SPACE CAB	Tail Lift	Tuckaway
Fuel Type	Diesel	Gearbox	AUTOMATIC		
Colour	WHITE				
Tyres					
NSF	NSI1	NSI2	NS	3	NSI4
OSF	OSI1	OSI2	os	3	OSI4
Spare	NSO1	NSO2	NS	D3	NSO4
	OS01	OSO2	os	D3	OSO4

Features

- Bluetooth connection Air conditioning
- Cruise control
- Front electric windows
- Park assist cameraCentral locking
- Digital radioCloth seat trim

Photos

























Condition Check



Damage Photos



1: Bonnet Chipped Multiple Chips



2: Bumper Front Chipped Multiple Chips



3: Bumper Front Scratched Over 100mm Thru Paint



4: Qtr Panel nsr Hole Over 10mm



5: Screen Front Chipped Over 10mm



6: Fascia Panel Soiled Heavy

Interior

Carpet Condition Seat Condition	OK OK		Upholstery Condition Odour	Poor -	
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		ОК	DPF light illuminated		OK
ABS light illuminated		OK			