

VEHICLE INSPECTION REPORT

BD73VSY

Peugeot Boxer 2.2 BlueHDi H2 140ps Professional

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 30/11/2023

VIN VF3YDBPFCPG053831

CAP Below £11,150.00

Year 2023

Body Style Panel Van L4

Gearbox MANUAL

Mileage 31,249 Miles Not Warranted

MOT Due 29/11/2026

Gears 6

Fuel Type Diesel

CAP Clean £13,450.00

Colour WHITE

CAP Average £12,650.00

AD-BLUE, SIDE LOAD DOOR, E/MIRRORS, DEADLOCKS (WITH KEYS)

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Cruise control
- Navigation system
- Park assist camera
- Rear parking sensor
- Auxiliary input socket
- Digital radio
- Air conditioning
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Door Mirror Assy nsf
Broken
Replace



4: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm



5: Qtr Panel nsr
Dented
Over 30mm



6: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



7: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



8: Qtr Panel nsr
Scratched
UpTo 25mm Not Thru Paint



9: Door nsr
Scratched
Over 25mm Thru Paint




10: Door nsr
Dented
Over 30mm



11: Door nsr
Dented
With Paint Damage




12: Door osr
Dented
With Paint Damage



13: Door osr
Scratched
Over 25mm Thru Paint



14: Door osr
Dented
With Paint Damage



15: Door osr
Dented
With Paint Damage



16: Door osr
Dented
Over 30mm



17: Bumper Rear
Cracked
Over 25mm



18: C Post os
Scratched
Over 25mm Thru Paint



19: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



20: Qtr Panel osr
Scratched
Over 25mm Thru Paint



21: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



22: Door osf
Dented
With Paint Damage



23:



24: Door osf
Dented
With Paint Damage



25: Door osf
Dented
With Paint Damage



26: Door osf
Dented
With Paint Damage



27: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



28: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		