

VEHICLE INSPECTION REPORT

DV73PXW

Vauxhall Vivaro 3100 2.0D 145PS PRIME

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 27/09/2023

VIN VXEVFEHTMP7855868

CAP Below £11,000.00

Year 2023

Body Style Panel Van L2

Gearbox MANUAL

Mileage 24,518 Miles Not Warranted

MOT Due 26/09/2026

Gears 6

Fuel Type Diesel

CAP Clean £13,200.00

Colour BLACK

CAP Average £12,450.00

AD-BLUE, TWIN SIDE LOAD DOOR, E/ MIRRORS

Tyres

NSF

NSR

OSF

OSR


Spare

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Panel Front
Scratched
Over 25mm Thru Paint



3: Panel Front
Scratched
Over 25mm Thru Paint



4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Wing nsf
Dented
Over 30mm



6: Other
N/A
N/A



7: Door osr
Scratched
Over 25mm Thru Paint



8: Door osr
Dented
Over 30mm



9: Door osr
Dented
With Paint Damage



10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Qtr Panel osr
Scratched
Over 25mm Thru Paint



16: Qtr Panel osr
Scratched
Over 25mm Thru Paint



17: Qtr Panel osr
Scratched
Over 25mm Thru Paint



18: Qtr Panel osr
Scratched
Over 25mm Thru Paint



19: Wing osf
Dented
Over 30mm



20: Wing osf
Scratched
Over 25mm Thru Paint



21: Door osf
Chipped
Edge Chip



22: Seat Base Cover osf
Soiled
Heavy



23: Seat Base Cover nsf
Soiled
Heavy



24: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		