

VEHICLE INSPECTION REPORT

DV73PYA

Vauxhall Vivaro 3100 2.0 145PS PRIME

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 27/09/2023

Year 2023

Mileage 15,634 Miles Not Warranted

Fuel Type Diesel

Colour BLACK

VIN VXEVFHTMP7856862

Body Style Panel Van L2

MOT Due 26/09/2026

CAP Clean £14,450.00

CAP Average £13,600.00

CAP Below £12,000.00

Gearbox MANUAL

Gears 6

AD-BLUE, TWIN SIDE LOAD DOOR, E/ MIRRORS

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Panel Front
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Panel Front
Scratched
Over 25mm Not Thru Paint



4: Wing nsf
Scratched
Over 25mm Thru Paint




5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Door nsf
Dented
Over 30mm



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



12: Door nsr
Scratched
Over 25mm Thru Paint



13: Door nsr
Scratched
Over 25mm Thru Paint



14: Lamp osr
Broken
Replace




15: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



16: Qtr Panel osr
Scratched
Over 25mm Thru Paint



17: Qtr Panel osr
Dented
With Paint Damage



18: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



19: Qtr Panel osr
Scratched
Over 25mm Thru Paint



20: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



21: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



22: Door osf
Dented
With Paint Damage



23: Door osf
Chipped
Edge Chip



24: Door osf
Scratched
Over 25mm Thru Paint




25: Wing osf
Dented
With Paint Damage




26: Door osf
Dented
Over 30mm



27: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



28: Seat Base Cover nsf
Soiled
Heavy



29: Seat Base Cover nsf
Soiled
Heavy



30: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK		