

VEHICLE INSPECTION REPORT

YA70DBZ

Mercedes-Benz Sprinter 315 3.5 PROGRESSIVE

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 25/01/2021

Year 2021

Mileage 129,909 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN W1V9076352P303518

Body Style Panel Van L3

MOT Due Expired

CAP Clean £11,100.00

CAP Average £10,100.00

CAP Below £8,475.00

Gearbox MANUAL

*WARNING LIGHT ON DASH**KEY FOB INOP, NO REAR ACCESS* AD-BLUE, SIDE LOAD DOOR

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Drivers airbag
- Cruise control
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front
Insecure
Action Required



4: Wing nsf
Dented
Over 30mm



5: Wing nsf
Dented
Over 30mm



6: Door nsf
Dented
Over 30mm



7: Qtr Panel nsr
Dented
Over 30mm



8: Qtr Panel nsr
Dented
Over 30mm



9: Qtr Panel nsr
Dented
Over 30mm



10: Door nsr
Dented
Over 30mm



11: Door nsr
Dented
Over 30mm



12: Door nsr
Dented
Over 30mm



13: Badgedecal Rear
Broken
Replace



14: Door osr
Dented
With Paint Damage



15: Door osr
Dented
With Paint Damage



16: Door osr
Dented
With Paint Damage



17: Door osr
Dented
Over 30mm



18: Qtr Panel osr
Dented
With Paint Damage



19: Qtr Panel osr
Scratched
Over 25mm Thru Paint



20: Qtr Panel osr
Dented
With Paint Damage



21: Qtr Panel osr
Dented
With Paint Damage



22: Qtr Panel osr
Scratched
Over 25mm Thru Paint



23: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



24: Qtr Panel osr
Scratched
Over 25mm Thru Paint



25: Qtr Panel osr
Scratched
Over 25mm Thru Paint



26: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



27: Qtr Panel osr
Dented
With Paint Damage



28: Qtr Panel osr
Dented
With Paint Damage



29: C Post os
Dented
With Paint Damage



30: Door osf
Dented
Over 30mm



31: Door osf
Dented
Over 30mm



32: Door osf
Dented
With Paint Damage



33: Door Moulding osf
Missing
Replace



34: Wing osf
Dented
With Paint Damage



35: Wing osf
Dented
Over 30mm



36: Bumper Front
Insecure
Action Required



37: Screen Front
Chipped
UpTo 10mm



38: Carpets Front
Torn
Over 10mm



39: Seat Base Cover osf
Holed
Over 3mm



40: Seat Base Cover nsf
Soiled
Heavy



41: Dash Warning Lights
Displayed
No Action



42: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	Poor	Odour	Yes
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	Fault
Airbag light illuminated	Fault		
ABS light illuminated	OK		