

VEHICLE INSPECTION REPORT

YH20UES

Mercedes-Benz Sprinter 314CDI 3.5t H2 Van

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 30/06/2020

Year 2020

Mileage 140,202 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN W1V9076352P200773

Body Style Panel Van L3

MOT Due 28/01/2026

CAP Clean £7,775.00

CAP Average £6,950.00

CAP Below £5,725.00

Gearbox MANUAL

AD-BLUE, SIDE LOAD DOOR

Tyres

NSF

NSR

OSF

OSR


Spare

Features

- Bluetooth connection
- Drivers airbag
- Cruise control
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Dented
Over 30mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front Moulding
Missing
Replace



4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm



6: Fuel Flap
Dented
Over 30mm



7: Door Moulding nsf
Scuffed (Unpainted)
UpTo 100mm



8: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



9: Qtr Panel nsr
Dented
Over 30mm



10: Qtr Panel Moulding ns
Broken
Replace



11: Qtr Panel nsr
Dented
Over 30mm



12: Qtr Panel nsr
Dented
With Paint Damage



13: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



14: Qtr Panel nsr
Dented
With Paint Damage




15: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



16: Lamp nsr
Broken
Replace



17: Door nsr
Poor Previous Repair
Poor Paint



18: Door nsr
Dented
Over 30mm




19: Door nsr
Dented
With Paint Damage



20: Door osr
Dented
With Paint Damage



21: Door osr
Dented
Over 30mm



22: Door osr
Dented
With Paint Damage



23: C Post ns
Dented
With Paint Damage



24: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



25: Qtr Panel osr
Dented
With Paint Damage



26: Qtr Panel osr
Dented
With Paint Damage



27: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



28: Qtr Panel osr
Dented
With Paint Damage



29: Qtr Panel osr
Dented
Over 30mm



30: Qtr Panel osr
Dented
Over 30mm



31: Qtr Panel osr
Dented
With Paint Damage



32: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



33: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



34: Door Moulding osf
Scuffed (Unpainted)
Up To 100mm



35: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



36: Door osf
Scratched
Over 25mm Thru Paint



37: Bumper Front
Insecure
Action Required



38: Screen Front
Chipped
Over 10mm



39: Seat Base Cover osf
Torn
Over 3mm



40: Seat Base Cover nsf
Burn
Over 3mm

Interior

| | | | | | |
|-----------------------|--|------|-----------------------|--|----|
| Carpet Condition | | OK | Upholstery Condition | | OK |
| Seat Condition | | Poor | Odour | | No |
| Engine Runs | | OK | No Excessive Smoking | | OK |
| EML light illuminated | | OK | DPF light illuminated | | OK |
| ABS light illuminated | | OK | | | |