

VEHICLE INSPECTION REPORT

YH20UET

Mercedes-Benz Sprinter 314 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 13/07/2020

Year 2020

Mileage 125,050 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN WDB9076352P176469

Body Style Panel Van L3

MOT Due 12/08/2025

CAP Clean £8,200.00

CAP Average £7,325.00

CAP Below £6,025.00

AD-BLUE, SIDE LOAD DOOR, DEADLOCKS (WITH KEYS)

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Drivers airbag
- Cruise control
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Roof
Dented
With Paint Damage



2: Roof
Dented
With Paint Damage



3: Bonnet
Dented
Over 30mm



4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Bonnet
Chipped
Multiple Chips



6: Bonnet
Dented
With Paint Damage



7: Bonnet
Dented
With Paint Damage



8: Bumper Front
Cracked
Over 25mm



9: Wing nsf
Dented
With Paint Damage



10: Wing nsf
Dented
Over 30mm



11: Wing nsf
Dented
With Paint Damage



12: Door nsf
Dented
With Paint Damage



13: Door nsf
Dented
With Paint Damage



14: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



15: Qtr Panel nsr
Dented
Over 30mm



16: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



17: Qtr Panel nsr
Dented
With Paint Damage



18: Qtr Panel nsr
Dented
Over 30mm



19: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



20: Qtr Panel nsr
Dented
With Paint Damage



21: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



22: Qtr Panel nsr
Dented
Over 30mm



23: Qtr Panel nsr
Dented
With Paint Damage



24: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



25: Qtr Panel nsr
Dented
Over 30mm



26: Qtr Panel nsr
Dented
With Paint Damage



27: Qtr Panel nsr
Dented
With Paint Damage



28: Qtr Panel nsr
Dented
Over 30mm



29: Door nsr
Dented
With Paint Damage



30: Door nsr
Dented
With Paint Damage



31: Door nsr
Dented
Over 30mm



32: Door nsr
Dented
Over 30mm



33: Door nsr
Dented
Over 30mm



34: Door nsr
Dented
Over 30mm



35: Door osr
Dented
Over 30mm



36: Badgedecal Rear
Broken
Replace



37: Door osr
Dented
Over 30mm



38: Door osr
Dented
Over 30mm



39: Qtr Panel osr
Dented
Over 30mm



40: Qtr Panel osr
Dented
Over 30mm



41: Qtr Panel osr
Dented
With Paint Damage



42: Qtr Panel osr
Dented
Over 30mm



43: Qtr Panel osr
Dented
With Paint Damage



44: Qtr Panel osr
Dented
With Paint Damage



45: Qtr Panel osr
Dented
Over 30mm



46: Qtr Panel osr
Scratched
Over 25mm Thru Paint



47: Qtr Panel osr
Scratched
Over 25mm Thru Paint



48: Qtr Panel osr
Dented
Over 30mm



49: Qtr Panel osr
Dented
With Paint Damage



50: Qtr Panel osr
Dented
Over 30mm



51: Qtr Panel osf
Scratched
Over 25mm Thru Paint



52: Door osf
Dented
Over 30mm



53: Door osf
Dented
With Paint Damage



54: Wing osf
Dented
With Paint Damage



55: Door Moulding osf
Missing
Replace



56: Seat Base Cover osf
Torn
Over 3mm



57: Carpets Front
Torn
Over 10mm



58: Seat Base Cover nsf
Soiled
Heavy



59: Door Pad nsf
Soiled
Heavy

Interior

Carpet Condition	Poor		Upholstery Condition	Poor
Seat Condition	Poor		Odour	No
Engine Runs	OK		No Excessive Smoking	OK
EML light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK			