

VEHICLE INSPECTION REPORT

YH20UEV

Mercedes-Benz Sprinter 314 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 13/07/2020

Year 2020

Mileage 108,064 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN W1V9076352P201180

Body Style Panel Van L3

MOT Due 26/07/2025

CAP Clean £8,675.00

CAP Average £7,750.00

CAP Below £6,375.00

Gearbox MANUAL

AD-BLUE, SIDE LOAD DOOR,

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Drivers airbag
- Cruise control
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Bonnet
Scratched
Over 25mm Thru Paint



3: Bonnet
Chipped
Multiple Chips



4: Bumper Front
Dented
Over 30mm



5: Wing nsf
Dented
Over 30mm



6: Wing nsf
Dented
Over 30mm



7: Door nsf
Dented
Over 30mm



8: Fuel Flap
Dented
Over 30mm



9: Qtr Panel nsr
Dented
With Paint Damage



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



12: Qtr Panel nsr
Dented
Over 30mm



13: Qtr Panel nsr
Dented
Over 30mm



14: Door nsr
Dented
With Paint Damage



15: Door osr
Dented
With Paint Damage



16: Door osr
Dented
Over 30mm



17: Badgedecal Rear
Broken
Replace



18: Door osr
Dented
Over 30mm



19: Door osr
Dented
Over 30mm



20: Door osr
Dented
Over 30mm



21: Door osr
Dented
Over 30mm



22: Bumper Rear
Scratched
Over 100mm Thru Paint



23: Qtr Panel osr
Dented
With Paint Damage



24: Qtr Panel osr
Scratched
Over 25mm Thru Paint



25: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



26: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



27: Door osf
Scratched
Over 25mm Thru Paint



28: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



29: Carpets Front
Holed
Over 3mm



30: Seat Base Cover osf
Torn
Over 3mm



31: Seat Base Cover nsf
Holed
Over 3mm



32: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
Airbag light illuminated	Fault		
ABS light illuminated	OK		