

VEHICLE INSPECTION REPORT

YK70EFW

Mercedes-Benz Sprinter 315 3.5 PROGRESSIVE

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 03/12/2020

Year 2020

Mileage 108,303 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN W1V9076352P309018

Body Style Panel Van L3

MOT Due 19/12/2025

CAP Clean £11,600.00

CAP Average £10,350.00

CAP Below £8,475.00

Gearbox MANUAL

AD-BLUE, SIDE LOAD DOOR

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Bluetooth connection
- Drivers airbag
- Cruise control
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Roof
Dented
Over 30mm



2: Roof
Dented
With Paint Damage



3: Bonnet
Chipped
Multiple Chips



4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Qtr Panel nsr
Dented
Over 30mm



6: Qtr Panel nsr
Dented
With Paint Damage



7: Qtr Panel nsr
Dented
With Paint Damage



8: Qtr Panel nsr
Dented
With Paint Damage



9: Qtr Panel Moulding ns
Broken
Replace



10: Qtr Panel nsr
Dented
With Paint Damage



11: Qtr Panel nsr
Dented
With Paint Damage



12: Door nsr
Dented
With Paint Damage



13: Door nsr
Dented
Over 30mm



14: Door osr
Dented
Over 30mm



15: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



16: Qtr Panel osr
Dented
Over 30mm



17: Qtr Panel osr
Dented
Over 30mm



18: Qtr Panel osr
Dented
Over 30mm



19: Qtr Panel osr
Scratched
Over 25mm Thru Paint



20: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



21: Qtr Panel osr
Dented
With Paint Damage



22: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



23: Qtr Panel osr
Scratched
Over 25mm Thru Paint



24: Qtr Panel osr
Dented
With Paint Damage



25: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



26: Door osf
Dented
With Paint Damage



27: Wing osf
Dented
With Paint Damage



28: Screen Front
Chipped
Over 10mm



29: Carpets Front
Holed
Over 3mm



30: Seat Base Cover osf
Torn
Over 3mm



31: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		