

VEHICLE INSPECTION REPORT

YK70EFZ

Mercedes-Benz Sprinter 3.5t H2 Progressive Van

Non Runner
Inspection

Serious Damage?	No	Vehicle	
		VAT	Plus VAT
		V5	Buyer To Apply

Details

Reg. date	03/12/2020	Colour	WHITE	CAP Clean	£11,900.00
Year	2020	VIN	W1V9076352P309021	CAP Average	£10,600.00
Mileage	TBC	Body Style	Panel Van	CAP Below	£8,675.00
Fuel Type	Diesel	MOT Due	Expired	Gearbox	MANUAL

NON RUNNER - DOES NOT START, GEARBOX ISSUES, PARTS REMOVED AD-BLUE, SIDE LOAD DOOR

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Drivers airbag
- Cruise control
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Unclassified
Major Parts Missing
Report Only



2: Unclassified
Major Parts Missing
Report Only



3: Bonnet
Dented
With Paint Damage



4: Bonnet
Chipped
Multiple Chips



5: Roof
Dented
With Paint Damage



6: Bumper Front
Scratched
Over 100mm Thru Paint



7: Wing nsf
Dented
With Paint Damage



8: Wing nsf
Dented
Over 30mm



9: Wing nsf
Dented
Over 30mm



10: Wing nsf
Scratched
Over 25mm Thru Paint



11: Door nsf
Dented
With Paint Damage



12: Door Moulding nsf
Missing
Replace



13: Door nsf
Dented
Over 30mm



14: Door nsf
Dented
Over 30mm



15: B Post ns
Dented
Over 30mm



16: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm



17: Qtr Panel nsr
Dented
Over 30mm



18: Qtr Panel nsr
Hole
Over 10mm



19: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



20: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



21: Qtr Panel nsr
Dented
Over 30mm



22: Unclassified
Substantial Accident Damage
Report Only



23: Qtr Panel nsr
Dented
Over 30mm




24: Door osr
Dented
With Paint Damage



25: Door osr
Dented
With Paint Damage



26: Badgedecal Rear
Broken
Replace



27: Door osr
Dented
Over 30mm



28: C Post os
Scratched
Over 25mm Thru Paint



29: Qtr Panel osr
Scratched
Over 25mm Thru Paint



30: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



31: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



32: Qtr Panel osr
Dented
With Paint Damage



33: Qtr Panel osr
Scratched
Over 25mm Thru Paint



34: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



35: Qtr Panel osr
Dented
With Paint Damage



36: Qtr Panel osr
Dented
Over 30mm



37: Qtr Panel osr
Dented
Over 30mm



38: Qtr Panel Moulding os
Broken
Replace



39: Door osf
Dented
Over 30mm



40: Door osf
Dented
Over 30mm



41: Door osf
Dented
With Paint Damage



42: Door Moulding osf
Missing
Replace



43: Door Moulding osf
Missing
Replace



44: Wing osf
Dented
Over 30mm



45: Bumper Front
Hole
Over 25mm



46: Wing osf
Dented
Over 30mm



47: Door Pad osf
Soiled
Heavy



48: Switches And Controls
Missing
Replace



49: Seat Base Cover osf
Torn
Over 3mm



50: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	Fault		